NO 🔯

## CORNER RECORD Mt Diablo 18E 16N Placer CALIFORNIA MERIDIAN COUNTY OF CONTROL [ OTHER | RANCHO | MEANDER CORNER TYPE: GOV'T. CORNER CORNER IDENTIFICATION - DATE OF VISIT \_\_\_\_\_ Brockway Vista Subdivision D/16REESTABLISHED OBLITERATED CORNER REBUILT TO FOUND AND TAGGED CORNER - LEFT AS FOUND PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH Found a 3/4" pipe approximately 40" long. The upper 18" was bent over below the Upon inspection the upper end showed signs of having been broken off at the approximate ground level. PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED The pipe was straightened as best was possible and resulting cracks occurred in the upper 12". A 1/2" rebar with a RCE 20257 cap was inserted into the pipe for re-enforcement. The pipe was replaced in the ground in the same position from which it was removed. The top was set at the present ground level. CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD STATIONS USED: NGS (USC & GS) STATE COUNTY COUNTY STATION STATION ZONE \_\_\_\_ ELEVATION \_\_\_\_ NORTHINGS (Y) \_\_\_\_ EASTINGS (X) \_\_\_\_ (Fold) SKETCH: (Include reference tie or witness points, remarks and topo of area) 0 = U.S. MEANDER CORNER Par BROCKWAY VISTA SUBDIVISION D/16. ( ) = FOUND 3/4" PIPE WITH BRASS CAP SECTION 19 STAMPED LS 2839 1980 Per North edge at centarline of concrete Telephone Vault. RECORD OF SURVEY 8/63. SECTION 13 N.T.S. East face of Z'/2" metal post. 6' Chainlink fence S 73° 34 E (857.58) 857.48° (857.48° Ros. 8/63) 31

- Face of 22" metal post towards corner. SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED NOV 30 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY AND EXAMINED AND FILED DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOU. 29 LAND SIGNED: DOCUMENT No .. Exp 12-31-88 L.S. or R.C.E. No.t. STATEMENT ON BACK OF SHEET YES [ RICHARD L. JENSEN